

**RECEIVING INSPECTION REPORT**  
**HYCON MFG. COMPANY**

No 128073

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080188-6

RECEIVED FROM

DATE REC'D

P. O. NO.

1013-77

CHARGE TO

QUANTITY  
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPR. NUMBER	BUY OUT CODE NO.	VENDOR PACKING SLIP NO.	ACCT. OR R. W. O. NO.	S. O. NO.
322	600300	20010	0	0	00	00	00			

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

738266 BEARING BRACKET ASSY

✓

INSTR FIL 2007

J. E. Johnson  
M. L. Koenig

RECEIVED  
BY

INSPECTED  
BY

Quar

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.

**RECEIVING INSPECTION REPORT**  
**HYCON MFG. COMPANY**  
2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128075

RECEIVED FROM

DATE REC'D

P. O. NO.

2-24-59

CHARGE TO

QUANTITY  
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPR. NUMBER	BUY OUT CODE NO.	VENDOR PACKING SLIP NO.	ACCT. OR R. W. O. NO.	S. O. NO.
322	600300	20013	0	0	00	00	00			

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

738265 WIRE ASSEMBLY TENSION SENSOR

✓

RET 3244

AT SUPPLEMENT 108 / 128055

J. E. Johnson  
M. L. Koenig

RECEIVED  
BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080188-6

REJECTS RETURNED  
ON SHIP. MEMO NO.